

Michael O Leavitt Governor Robert L Morgan Executive Director

Lowell P Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Ulah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY www.nr.utah.gov

July 30, 2003

TO:

Minerals File

FROM:

Tom Munson, Senior Reclamation Hydrologist

SUBJECT:

Site Inspection, David Penney, Sliver #3-#4, S/001/057, Beaver County, Utah

Date of Inspection:

June 26, 2003

Time of Inspection:

1:00-2:00 p.m.

Conditions:

Sunny

Participants:

Tom Munson, DOGM

Purpose of Inspection:

To perform an annual inspection of the property.

Observations:

I did not GPS the site, because Mr. Ginouves of the Cedar City BLM office has kept good records and GPS files on this site as it is located entirely on BLM land. There is a new road that has been built on the east and north side of this property, which comes up the canyon from the main access road. It comes up the hill until it reaches the new quarry site, now making it possible for a semitruck to come up the backside of this property, turn around and then leave the same way it came. This makes this particular site more advantageous for the miner, but increases the amount of disturbance. The attached GPS map shows the property at greater then five acres and makes this mine a Large Mining Operation. The BLM holds a National Bond allocating \$20,000 for reclamation on this property.

Conclusions and Recommendations:

I contacted Mr. Ginouves to get him to re-GPS this site so we would have an accurate acreage as to how much disturbance actually exists at the site. On July 9, 2003, Mr. Ginouves GPS'd the overall disturbance. The USGS quadrangle is Cave Canyon. This property is located in the S1/2 of the SW1/4 of Section 17 and the S1/2 of the SE1/4 of Section 18, T29S, R9W. The disturbance associated with the mine site and access road on the backside of the pit is 4.74 acres. The access road, which takes off from existing access road and runs up the canyon is approximately .73 acres, making a total of 5.5 acres of disturbance found within this site. It is my recommendation that Mr. Penney permit this mine as a Large Mining Operation and that the Division generate a map that will help Mr. Penney be able to put down on paper what his mining plans are, in terms of reclamation and the requirements of the LMO. Once the plan is approved, the Division can verify that Mr. Penney has enough bond money to reclaim the Picasso marble site and that the Division can access the nationwide bond the BLM holds.


jb

David Penney, operator
 Ed Ginouves, BLM

O:\M001-Beaver\S010057-Silver3-4\inspections\insp-06262003.doc



S/001/057 Sliver # 3-4 David Penney



500 0 500 1000 1500 2000 2500 3000 3500 Feet



Access Road - .73 acres Mine Disturbance Area- 4.74 Acres

Inspection performed and GPS data collected by Ed Ginouves of BLM - July 9, 2003 USGS Quadrangle - Cave Canyon(Q3211) Location: S1/2 of SW1/4, Sec 17 S1/2 of SE 1/4, Sec 18 T29S, R9W



This product may not meet DOGM standards for accurracy and content. Different data sources and input scales may cause some misalignment of data layers.

ATTACHMENT

Photographs S/001/057, Sliver 3-4,David Penney Inspection Dated: 6/19/2003; Report Dated: 7/17/2003



Photo 1 - north part of mine site pad and pit



Photo 2 - Outcrop of Ore Body



Photo 3 - new road up backside



Photo 4 - new road up backside

Page 2 S/001/057 Silver 3-4 7/17/2003



Photo 5 - new road up backside



Photo 6 - new road up backside



Photo 7 - Upper pad looking west



Photo 8 - Where road from backside meets pad

Page 3 S/001/057 Silver 3-4 7/17/2003



Photo 9 - Active Pit Area



Photo 10 - Road adjacent to pit.